

Ref: 2624/L/177

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 177, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/178

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 178, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/179

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 179, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/180

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 180, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/181

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 181, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/182

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 182, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/183

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 183 , Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/184

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 184, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/185

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 185, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/186

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 186, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/187

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 187, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/190

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

03/02/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 190, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/191

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 191, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/192

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 192, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/193

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 193, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/194

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 194, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/195

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 195 , Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/196

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

03/02/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 196, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/197

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 197 , Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/198

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 198, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/201

Project Ref: 2624/P/1163

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

16/12/2020

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 201, Amity Narangba Stage 8A**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Broddie Krebs
Lab Supervisor
For Brisbane North
Construction Sciences

Ref: 2624/L/202

Project Ref: 2624/P/1163

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

16/12/2020

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 202, Amity Narangba Stage 8A**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Broddie Krebs
Lab Supervisor
For Brisbane North
Construction Sciences

Ref: 2624/L/203

Project Ref: 2624/P/1163

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

16/12/2020

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 203, Amity Narangba Stage 8A**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Broddie Krebs
Lab Supervisor
For Brisbane North
Construction Sciences

Ref: 2624/L/204

Project Ref: 2624/P/1163

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

16/12/2020

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 204, Amity Narangba Stage 8A**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Broddie Krebs
Lab Supervisor
For Brisbane North
Construction Sciences

Ref: 2624/L/205

Project Ref: 2624/P/1163

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

16/12/2020

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 205, Amity Narangba Stage 8A**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Broddie Krebs
Lab Supervisor
For Brisbane North
Construction Sciences

Ref: 2624/L/214

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 214, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/215

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 215, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/216

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 216 , Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/217

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 217, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/218

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 218, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/219

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 219, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences

Ref: 2624/L/220

Project Ref: 2624/P/1251

**Construction Sciences Pty
Ltd** ABN 74 128 806 735

18/01/2022

2 Aldinga St
Brendale QLD 4500
Australia

CCA Winslow
1587 Ipswich Road
Rocklea QLD

Phone: 61 7 3865 3212
**www.constructionscience
s.net**

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 220, Amity Narangba - Stage 8B**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill"

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Mitchell Eaton
Senior Technician
For Brisbane North
Construction Sciences